



Release Notes

Product Name: RC-308

Current Version: Type

Туре	Number	Date
Firmware	4.0.48.61814	November 2021
Software	_	_
Web	_	_
Hardware	_	_

RN Date: November 14, 2021

Reference: 17917

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-308	Any	Yes	Yes

Summary:

- Firmware upgrade
- Added new features

Codependency with Other Products and Software:

There is no codependency with other products or software.





Release Notes

Product Name: RC-308

Current Version:

Туре	Number	Date
Firmware	4.0.48.61814	November 2021
Software	_	_
Web	_	_
Hardware	_	_

RN Date: November 14, 2021

Reference: 17917

New Features:

	ons lights test at power	up, even if no K-Config projec	t is programmed in the device
Added ET	H-to-RS-232 tunneling a	ability similar to FC-6 and other	er gateway devices.
TCP Port	1:		
5001			
TCP Port	2:		
5002			
Default va	lues for the RS-232 port	ts:	
Data Bits	: 8		
Baud Rat	e: 9600		
Stop Bits	: 1		
Us	sers can change defau	ult values by the Protocol 3	000 UART command:
Command	- UART	Command Type - Commu	nication
0	l Name	Permission	Transparency
Command			
Set:	UART	Administrator	Public
	UART?	Administrator End User	Public Public
Set:	UART?		
Set: Get:	UART?	End User Syntax:	
Set: Get: Description	UART? on Set com port	End User Syntax:	Public
Set: Get: Description Set:	UART? Set com port configuration Get com port configuration	End User Syntax: # UART SP COM_Num, bau	Public

Get: ~ nn@ UART [sp | COM_Num, baud_rate, data_bit, parity, stop_bit, serial1_type, 485_term | CR LF |

Parameters

COM_Num - 1-4

baud_rate - 9600 - 115200

data_bit - 7-8

parity - 'N', 'O', 'E', 'M', 'S'

stop_bit - 1-2



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com Web: www.kramerav.com





Release Notes

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
13026	WEB: The 'set' button of the 'Manual' (device date & time) and 'Time zone' is always enabled.
13029	In some cases, after FW upgrade to slave via TCP, the master loses ping.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
1428, 1429	RS-232 Tx/Rx: When performing a load RS-232 communication test, one of every thousand characters may be lost (Rx+Tx simultaneously) and cause sending/receiving command failure.

Preceding Version: 4.0.47.53564





Product Name: RC-308

Current Version: Type

Туре	Number	Date
Firmware	4.0.47.53564	June 2019
Software	_	_
Web	_	_
Hardware	_	_

RN Date: June 25, 2019

Reference: 15394

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-308	Any	Yes	Yes

Technical Notes:

Fixed a bug.

Codependency with Other Products and Software:

• There is no codependency with other products or software.





Product Name: RC-308

Current Version: Type

Туре	Number	Date
Firmware	4.0.47.53564	June 2019
Software	_	_
Web	_	_
Hardware	_	_

RN Date: June 25, 2019

Reference: 15394

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
	Fixed an issued that slowed down the device.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
13026	WEB: The 'set' button of the 'Manual' (device date & time) and 'Time zone' is always enabled.
13029	In some cases, after FW upgrade to slave via TCP, the master loses ping.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
1428, 1429	RS-232 Tx/Rx: When performing a load RS-232 communication test, one of every thousand characters may be lost (Rx+Tx simultaneously) and cause
	sending/receiving command failure.

Preceding Version: 4.0.45.49251



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com





Product Name: RC-308

Current Version: Type Number Date

Firmware 4.0.45.49251 August 2018

Software – –
Web – –
Hardware – – –

RN Date: August 2018

Reference: 14391

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-308	Any	Yes	Yes

Technical Notes:

Added support for Kramer Control.

Codependency with Other Products and Software:

There is no codependency with other products or software.





Product Name: RC-308

Current Version: Type Number Date

Type	Nullibel	Date
Firmware	4.0.45.49251	August 2018
Software	_	_
Web	_	_
Hardware	_	_

RN Date: August 2018

Reference: 14391

The following changes were made in this version:

New Features:

New Feature Description
Added support for Kramer Control.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
1428, 1429	RS-232 Tx/Rx: When performing a load RS-232 communication test, one of every thousand characters may be lost (Rx+Tx simultaneously) and cause sending/receiving command failure.

Preceding Version: 4.0.11



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>





Product Name: RC-308

Current Version: Type Number Date

туре	Number	Date
Firmware	4.0.11	March 2018
Software	_	_
Web	_	_
Hardware	_	_

RN Date: March 2018

Reference: 12109

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-306	N/A	N/A	N/A
RC-308	N/A	N/A	N/A

Technical Notes:

• This is a release note for a new product.

Codependency with Other Products and Software:

Product Name	Comments
K-Config	





Product Name: RC-308

Current Version: Type Number Date

туре	Number	Date
Firmware	4.0.11	March 2018
Software	_	_
Web	_	_
Hardware	_	_

RN Date: March 2018

Reference: 12109

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/RC-308

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
1428, 1429	RS-232 Tx/Rx: When performing a load RS-232 communication test, one of every thousand characters may be lost (Rx+Tx simultaneously) and cause
	sending/receiving command failure.

Preceding Version: F - N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com