

## Release Notes

**Product Name:** VS-34FD

**Current Version:**

Type	Number	Date
Firmware	1.2_0002	October 2021
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** October 13, 2021

**Reference:** 17741-17799

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-34FD	Any	Yes	Yes
H2A-IN2-F34	Any	Yes	Yes
H2-IN2-F34	Any	Yes	Yes

### Technical Notes:

- New firmware (version 1.1\_0000) for module cards: H2A-IN2-F34, H2-IN2-F34; in addition to new VS-34FD chassis firmware.

### Summary:

- Fixed bugs.
- Added support for new module card: DTAXRD2P-OUT2-F34.

### Codependency with Other Products and Software:

Product Name	Comments
Modules	See ACCESSORIES & RELATED PRODUCTS tab at <a href="https://www.kramerav.com/product/VS-34FD">https://www.kramerav.com/product/VS-34FD</a>



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** VS-34FD

**Current Version:**

Type	Number	Date
Firmware	1.2_0002	October 2021
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** October 13, 2021

**Reference:** 17741-17799

### New Features:

	New Feature Description
	Added support for new module card: DTAXRD2P-OUT2-F34.

### Bugs Fixed:

QC ID	Fixed Bug Description
18824	Embedded Web Pages – Added PoE power supply enable/disable Protocol 3000 response.
18827	Embedded Web Pages – Port name labels are now reset to default values following a factory reset.
	H2A-IN2-F34, H2-IN2-F34 – New firmware (version 1.1_0000) fixes audio embedding issue.

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
15755	EDID Designer application tool does not support VS-34FD
18502	DTAXRD2-IN2-F34 and DTAXRC2-IN2-F34 do not support HDCP-OFF feature setting via the HDCP-MOD P3K command or Web page setting
18505	DTAXRD2-OUT2-F34 card switching speed 'Extra-Fast' setting does not show video in the output. Workaround: Use only 'Fast' (Default setting) or 'Normal' settings.
18819	Embedded Web Pages – Port name labels are not restored loading a configuration file.
18892	CPEDID Protocol 3000 command between DTAXRC2-OUT to DTAXRC2-IN ports causes the output card connected receiver to lock a non-standard resolution format in its output and causes unrecognized screen signal. Workaround: Reset the connected receiver extender TP-583RX.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

QC ID	Deferred Bug Description
18967	The following functions are not implemented: STO, RCL, OFF, DELAY front panel buttons and TAKE mode for I/O switching.
KMR-64072	DTAXRD2-OUT2-F34, DTAXRD2P-OUT2-F34 - Performing a firmware upgrade via K-Upload fails. <b>Workaround:</b> Perform upgrade via internal web GUI.
KMR-79713	DNS name-change through web page is not possible in this version. Setting it up through P3K is functioning properly.
KMR-79631	Re-configuring Extra-Range may cause audio loss of audio sources from local-card analog audio and matrix audio source. However, embedded audio is not affected. <b>Workaround:</b> Re-power the port after Extra-Range re-configuration. <b>Note:</b> The Extra-Range setup feature provides longer distance distribution by limiting the resolution to 1080p.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: 1.1\_0001



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-34FD

**Current Version:**

Type	Number	Date
Firmware	1.1_0001	November 2020
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 2, 2021

**Reference:** 17467

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-34FD	Any	Yes	Yes

### Technical Notes:

- New firmware for DTAXRD2-IN2-F34 and DTAXRD2-OUT2-F34 cards to support new chipset. Back compatible with existing chipset.
  - New FW version for DTAXRD2-IN2-F34: 1.1\_0000.
  - New FW version for DTAXRD2-OUT2-F34: 1.1\_0001.

### Codependency with Other Products and Software:

Product Name	Comments
Modules	See ACCESSORIES & RELATED PRODUCTS tab at <a href="https://www.kramerav.com/product/VS-34FD">https://www.kramerav.com/product/VS-34FD</a>



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-34FD

**Current Version:**

Type	Number	Date
Firmware	1.1_0001	November 2020
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 2, 2021

**Reference:** 17467

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
15755	EDID Designer application tool does not support VS-34FD
18502	DTAXRD2-IN2-F34 and DTAXRC2-IN2-F34 do not support HDCP-OFF feature setting via the HDCP-MOD P3K command or Web page setting
18505	DTAXRD2-OUT2-F34 card switching speed 'Extra-Fast' setting does not show video in the output. Workaround: Use only 'Fast' (Default setting) or 'Normal' settings.
18819	Embedded Web Pages – Port name labels are not restored loading a configuration file.
18824	Embedded Web Pages – PoE power supply enable/disable is missing a suitable Protocol 3000 response
18827	Embedded Web Pages – Port name labels are not reset to default values following a factory reset.
18892	CPEDID Protocol 3000 command between DTAXRC2-OUT to DTAXRC2-IN ports causes the output card connected receiver to lock a non-standard resolution format in its output and causes unrecognized screen signal. Workaround: Reset the connected receiver extender TP-583RX.
18967	The following functions are not implemented: STO, RCL, OFF, DELAY front panel buttons and TAKE mode for I/O switching.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** 1.1\_0001



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-34FD

**Current Version:**

Type	Number	Date
Firmware	1.1_0001	November 2020
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** November 29, 2020

**Reference:** 16736

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-34FD	Any	Yes	Yes

### Technical Notes:

- Added new features and Protocol 3000 commands.
- Fixed several bugs.

### Codependency with Other Products and Software:

Product Name	Comments
Modules	See ACCESSORIES & RELATED PRODUCTS tab at <a href="https://www.kramerav.com/product/VS-34FD">https://www.kramerav.com/product/VS-34FD</a>



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-34FD

**Current Version:**

Type	Number	Date
Firmware	1.1_0001	November 2020
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** November 29, 2020

**Reference:** 16736

### New Features:

	New Feature Description
	Added TCP port 6000 for a single TCP connection.
	Added chassis management status protocol commands for the following: temperature, fans speed, power supply voltage level, power supply presence, power supply remote indication and PoE power supply presence.
	Added fan control board information to MODULE-INFO? Protocol 3000 API command
	FW support in chassis fan control HW version to V1.1.0.

### Modifications:

QC ID	Modification Description
	Changed the performance parameter for output module card to 800mv.
	Embedded Web Pages: Improvements to Matrix View page.

### Bugs Fixed:

QC ID	Fixed Bug Description
18389	FW upgrade for cards are not supported when browsing with Microsoft Edge
18390	Configurations save is not supported when browsing with Microsoft Edge

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
15755	EDID Designer application tool does not support VS-34FD
18502	DTAXRD2-IN2-F34 and DTAXRC2-IN2-F34 do not support HDCP-OFF feature setting via the HDCP-MOD P3K command or Web page setting



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

QC ID	Deferred Bug Description
18505	DTAXRD2-OUT2-F34 card switching speed 'Extra-Fast' setting does not show video in the output. Workaround: Use only 'Fast' (Default setting) or 'Normal' settings.
18819	Embedded Web Pages – Port name labels are not restored loading a configuration file.
18824	Embedded Web Pages – PoE power supply enable/disable is missing a suitable Protocol 3000 response
18827	Embedded Web Pages – Port name labels are not reset to default values following a factory reset.
18892	CPEDID Protocol 3000 command between DTAXRC2-OUT to DTAXRC2-IN ports causes the output card connected receiver to lock a non-standard resolution format in its output and causes unrecognized screen signal. Workaround: Reset the connected receiver extender TP-583RX.
18967	The following functions are not implemented: STO, RCL, OFF, DELAY front panel buttons and TAKE mode for I/O switching.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: 01.00.0026



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)



## Release Notes History

**Product Name:** VS-34FD

**Current Version:**

Type	Number	Date
Firmware	01.00.0026	September 2020
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** November 15, 2020

**Reference:** 16841

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-34FD	Any	Yes	Yes

### Technical Notes:

New firmware for VGAA-OUT2-F34 card: version 1.2\_0001.

Fixed a bug in the VGAA-OUT2-F34 card.

### Codependency with Other Products and Software:

Product Name	Comments
Modules	See ACCESSORIES & RELATED PRODUCTS tab at <a href="https://www.kramerav.com/product/VS-34FD">https://www.kramerav.com/product/VS-34FD</a>



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-34FD

**Current Version:**

Type	Number	Date
Firmware	01.00.0026	September 2020
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** November 15, 2020

**Reference:** 16841

### Bugs Fixed:

QC ID	Fixed Bug Description
18623	VGAA-OUT2-F34 module card: Issue with reading the EDID of a connected display.

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
15755	EDID Designer application tool does not support VS-34FD
18389	FW upgrade for cards are not supported when browsing with Microsoft Edge
18390	Configurations save is not supported when browsing with Microsoft Edge
18502	DTAXRD2-IN2-F34 and DTAXRC2-IN2-F34 do not support HDCP-OFF feature setting via the HDCP-MOD P3K command or Web page setting
18505	DTAXRD2-OUT2-F34 card switching speed 'Extra-Fast' setting does not show video in the output. Workaround: Use only 'Fast' (Default setting) or 'Normal' settings.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** 01.00.0026



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-34FD

**Current Version:**

Type	Number	Date
Firmware	01.00.0026	September 2020
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** September 24, 2020

**Reference:** 07789

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-34FD	N/A	N/A	N/A

### Technical Notes:

- This is a release note for a new product.

### Codependency with Other Products and Software:

Product Name	Comments
Modules	See ACCESSORIES & RELATED PRODUCTS tab at <a href="https://www.kramerav.com/product/VS-34FD">https://www.kramerav.com/product/VS-34FD</a>



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VS-34FD

**Current Version:**

Type	Number	Date
Firmware	01.00.0026	September 2020
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** September 24, 2020

**Reference:** 07789

This is a release note for a new product. For a list of new product features see:

[www.kramerav.com/manual/VS-34FD](http://www.kramerav.com/manual/VS-34FD)

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
15755	EDID Designer application tool does not support VS-34FD
18389	FW upgrade for cards are not supported when browsing with Microsoft Edge
18390	Configurations save is not supported when browsing with Microsoft Edge
18502	DTAXRD2-IN2-F34 and DTAXRC2-IN2-F34 do not support HDCP-OFF feature setting via the HDCP-MOD P3K command or Web page setting
18505	DTAXRD2-OUT2-F34 card switching speed 'Extra-Fast' setting does not show video in the output. Workaround: Use only 'Fast' (Default setting) or 'Normal' settings.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)