

Release Note

Product Name: 691

Current Version:

| Ver.Type | Ver No. | Date |
|----------|------------|-----------|
| Firmware | 1.12.36658 | June 2017 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: June 2017

Reference: 10693

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| 691 | N/A | N/A | N/A |
| | | | |

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Note History

Product Name: 691

| Current Version: | Ver.Type | Ver No. | Date |
|-------------------------|----------|------------|-----------|
| | Firmware | 1.12.36658 | June 2017 |
| | Software | – | – |
| | Web | – | – |
| | Hardware | – | – |

RN Date: June 2017

Reference: 10693

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/691>

Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description |
|-------|---|
| 10017 | WEB: Wrong HDCP status on output |
| 10748 | WEB: Remove the 5V cut-off timer option |
| 10845 | K-Upload: HDBT chipset burn via Ethernet fails rarely |

Known Limitations (including compatibility limitations):

| QC ID | Limitation Description |
|-------|------------------------|
| | None listed |

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com