

Release Note

Product Name: 692

Current Version:	Ver.Type	Ver No.	Date
	Firmware	1.12.36658	June 2017
	Software	–	–
	Web	–	–
	Hardware	–	–

RN Date: June 2017

Reference: 10693

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
692	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Note History

Product Name: 692

Current Version:

Ver.Type	Ver No.	Date
Firmware	1.12.36658	June 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: June 2017

Reference: 10693

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/692>

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
10803	Wrong analog audio output handling after power up
10804	Faulty audio temporary output following analog audio disconnection
10844	WEB: Wrong audio 2-channel setup handling
10846	K-Upload: HDBT chipset burn via Ethernet fails rarely

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com