

## Release Notes

**Product Name:** FC-46H2

**Current Version:**

Type	Number	Date
Firmware	1.3.57926	September 2020
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** September 9, 2020

**Reference:** 16708

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
FC-46H2	Any	Yes	Yes

### Technical Notes:

- Fixed a bug.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.

### Bugs Fixed:

QC ID	Fixed Bug Description
18039	Sometimes no video on Power UP.

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
15518	No AUDIO LED status indication if ARC is active and CEC is not active.
15659	Need to reboot the device to exit DVI output mode.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
15534	<p>SONY TV: ARC works properly until TV is powered OFF and ON. After power ON, the TV's logical address changes and the CEC connection between the device and the Sony TV is lost. Workaround: Disconnect the device HDMI output port, restart the TV and reconnect the HDMI output again.</p>

**Preceding Version:** 1.3.53451



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** FC-46H2

**Current Version:**

Type	Number	Date
Firmware	1.3.53451	July 2019
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** July 4, 2019

**Reference:** 06740

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
FC-46H2	N/A	N/A	N/A

### Technical Notes:

- This is a release note for a new product.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** FC-46H2

**Current Version:**

Type	Number	Date
Firmware	1.3.53451	July 2019
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** July 4, 2019

**Reference:** 06740

This is a release note for a new product. For a list of new product features see:

[www.kramerav.com/manual/FC-46H2](http://www.kramerav.com/manual/FC-46H2)

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
15518	No AUDIO LED status indication if ARC is active and CEC is not active.
15659	Need to reboot the device to exit DVI output mode.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
15534	SONY TV: ARC works properly until TV is powered OFF and ON. After power ON, the TV's logical address changes and the CEC connection between the device and the Sony TV is lost. <b>Workaround:</b> Disconnect the device HDMI output port, restart the TV and reconnect the HDMI output again.

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)