

## Release Notes

**Product Name:** KDS-7-MNGR

**Current Version:**

Type	Number	Date
Firmware	0.7.6	December 2022
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** December 26, 2022

**Reference:** 18526

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KDS-7-MNGR	Any	Yes	Yes

### Summary:

- Fixed bugs.
- Added features.

### Codependency with Other Products and Software:

Product Name	Comments

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** KDS-7-MNGR

**Current Version:**

Type	Number	Date
Firmware	0.7.6	December 2022
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** December 26, 2022

**Reference:** 18526

### New Features:

	New Feature Description
1	IE browser is no longer supported.
2	#TEST-MOD, #FCT-MAC and #FCT-SN commands are supported.
3	#ADDUSER and #RMUSER API added.
4	HDMI UI with Home, Refresh, Forward and Back buttons was added.
5	Editing of group names is supported.

### Modifications:

	Modification Description
1	Video Wall Routing Page operation Improved.
2	The HDMI background image is the Kramer Logo.
3	UI improvements, such as an active/inactive button, etc.
4	Password security improved – a strong password is required when user changes password.
5	Default IP is now 192.168.1.39

### Bugs Fixed:

ID	Fixed Bug Description
	Low temperature boot fail issue fixed.
	Some TVs could not show the full HDMI UI – this issue is now fixed.
	Fixed the issue that Video Wall Routing page changes the IR/CEC/RS232 routing too.
GB-988	When importing a configuration file, the device changed according to the configuration file and not on the selection aet by the menu.
GB-987	Import feature did not work properly when security was set to on.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

ID	Fixed Bug Description
GB-973	In the security page, the radio button was active till the end of the line but selection was not carried out.
GB-943	The manager did not scan the network for changes automatically (only following refresh).
GB-902	Presets did not indicate which preset is active.
GB-844 GB-843	Import / export system files did not work properly.
GB-812	Heat Level temperature status displays an incorrect character for the Celsius degree. Should be "40".
GB-806	LCD menu page doesn't return to main page after exceeding the time out period.

### Bugs to Fix in Future Versions:

ID	Deferred Bug Description
GB-842	When trying to switch 2 encoders TO 1 decoder in Icon routing View from the HDMI output, the UUT performs reset in HDMI OUTPUT.

### Known Limitations (including compatibility limitations):

ID	Limitation Description

**Preceding Version:** 0.5.4



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** KDS-7-MNGR

**Current Version:**

Type	Number	Date
Firmware	0.5.4	June 2022
Software	–	–
Web	–	–
Hardware		

**RN Date:** July 3, 2022

**Reference:** 60-000790

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KDS-7-MNGR			

**IMPORTANT:** If you have a device with FW version lower than 0.5.4 (beta units), please consult with the Kramer Support Team for special FW update instructions.

### Summary:

This is a release note for a new product. To view the product's webpage, see:

<https://www.kramerav.com/il/product/KDS-7-MNGR>

### Codependency with Other Products and Software:

There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** KDS-7-MNGR

**Current Version:**

Type	Number	Date
Firmware	0.5.4	June 2022
Software	–	–
Web	–	–
Hardware		

**RN Date:** July 3, 2022

**Reference:** 60-000790

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KDS-7-MNGR		Y	

**IMPORTANT:** If you have a device with FW version less than 0.5.4 (beta units), please consult with the Kramer Support Team for special FW update instructions.

### Summary:

This is a release note for a new product. To view the product's webpage, see:

<https://www.kramerav.com/il/product/KDS-7-MNGR>

### Codependency with Other Products and Software:

There is no codependency with other products or software.

### Open Bugs to Fix in Future Versions:

ID	Deferred Bug Description
GB-844, GB-843	To import / export system files, you need to select "ALL".
GB-841	KDS-ROUTE? command does not display the encoder device name as expected.
GB-831	#TIME-LOC command does not support all time zones.
GB-821	Need to update the new Kramer address in the About page.
GB-812	Heat Level temperature status displays an incorrect character for the Celsius degree. Should be "40°"



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

ID	Deferred Bug Description
GB-806	LCD menu page doesn't return to main page after exceeding the time out period.
GB-706	#NET-IP command works only in UDP protocol.

### Known Limitations (including compatibility limitations):

ID	Limitation Description

Preceding Version: N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)