



## Release Notes

**Product Name:**

**MTX3-88-PR-PRO**

**Current Version:**

Type	Number	Date
Firmware	1.0.18.5	December 2025
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:**

December 25, 2025

**Reference:**

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
MTX3-88-PR-PRO	N/A	N/A	N/A

### Summary:

- New Feature
- Modifications
- Bug Fixes

### Codependency with Other Products and Software:

- There is no codependency with other products or software.

### New Feature:

ID	New Feature Description
1914	Added Increase/Decrease audio output P3K command(+/--).

### Modifications:

ID	Modifications Description
1802	Removed the GATEWAY toggle button from RS-232 and IR pages.
1870	Added Visual Feedback for Loaded Screen to Output Association.
1873	Added option to Splash Screen to Delete/Remove Images from Screen Library.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)



## Release Notes

ID	Modifications Description
1886	Removed RTMP option from webpage.
1907	GPIO>Digital Input: The webpage now shows the measured voltage level.
1925	Added a tooltip in the DSP webpage when trying to add an AEC channel but both AECs already in use.
1956	Changed configuring the HDBT ports such that HDBT IN 1 & 2 are not assigned in place of USB-C IN 1 & 2.
1978	Created option to individually disable a mirrored output.
2003	Added option to disable ETH from USB-C.
2029	Updated VLAN PASS THRU section to clarify that it is related to HDBT service only.

### Bug Fixes:

ID	Bug Fixes Description
1803	The response time for adjusting volume from the front panel was too slow. . .
1934	There was no audio output from MIC after reboot by control command sequence.
1937	: The USB Audio was not recognized as a host for USB-C 2.
1938	When adding/removing the audio port on the web AV&USB Settings>>Audio Pre-Config tab, it erased the routing table on the Routing>>Audio tab.
1958	Corrected the fallback default network gateway to 192.168.1.1.

**Preceding Version:** 1.0.17.3



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)



## Release Notes

**Product Name:**

**MTX3-88-PR-PRO**

**Current Version:**

Type	Number	Date
Firmware	1.0.17.3	March 2025
Software	—	—
Web	—	—
Hardware	—	—

**RN Date:**

March 25, 2025

**Reference:**

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
MTX3-88-PR-PRO	N/A	N/A	N/A

### Summary:

- This is a release note for a new product.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.

### Replaced Products:

- N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)



## Release Notes

**Product Name:**

**MTX3-88-PR-PRO**

**Current Version:**

Type	Number	Date
Firmware	1.0.18.5	December 2025
Software	—	—
Web	—	—
Hardware	—	—

**RN Date:**

December 25, 2025

**Reference:**

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
MTX3-88-PR-PRO	N/A	N/A	N/A

### Summary:

- New Feature
- Modifications
- Bug Fixes

### Codependency with Other Products and Software:

- There is no codependency with other products or software.

### New Feature:

ID	New Feature Description
1914	Added Increase/Decrease audio output P3K command(+/--).

### Modifications:

ID	Modifications Description
1802	Removed the GATEWAY toggle button from RS-232 and IR pages.
1870	Added Visual Feedback for Loaded Screen to Output Association.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)



## Release Notes

ID	Modifications Description
1873	Added option to Splash Screen to Delete/Remove Images from Screen Library.
1886	Removed RTMP option from webpage.
1907	GPIO>Digital Input: The webpage now shows the measured voltage level.
1925	Added a tooltip in the DSP webpage when trying to add an AEC channel but both AECs already in use.
1956	Changed configuring the HDBT ports such that HDBT IN 1 & 2 are not assigned in place of USB-C IN 1 & 2.
1978	Created option to individually disable a mirrored output.
2003	Added option to disable ETH from USB-C.
2029	Updated VLAN PASS THRU section to clarify that it is related to HDBT service only.

### Bug Fixes:

ID	Bug Fixes Description
1803	The response time for adjusting volume from the front panel was too slow. .
1934	There was no audio output from MIC after reboot by control command sequence.
1937	: The USB Audio was not recognized as a host for USB-C 2.
1938	When adding/removing the audio port on the web AV&USB Settings>>Audio Pre-Config tab, it erased the routing table on the Routing>>Audio tab.
1958	Corrected the fallback default network gateway to 192.168.1.1.

**Preceding Version:** 1.0.17.3



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)



## Release Notes

**Product Name:**

**MTX3-88-PR-PRO**

**Current Version:**

Type	Number	Date
Firmware	1.0.17.3	March 2025
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:**

March 25, 2025

**Reference:**

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/MTX3-88-PR-PRO>

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)