



**Current Product Version:** Per table below  
**Version Date:** December 2012 (Ver.2)  
**Reference:** 4016

**Kramer Products Affected:**

Product Name	Version Affected	Recommended for All Units	Only if Added Features are Required
PT-571 PT-572+ TP-573 TP-574 PT-571HDCP PT-572HDCP+ WP-571 WP-572	1600 0400   0600 0300	Yes and all earlier versions	N/A

**Technical Notes:**

- This note warns of a known power issue when connecting a PT/TP/WP-57x to a VM-114Hx.

**Codependency with Other Products and Software:**

Product Name	Version	Comments
VM-114H VM-114H2C VM-114H4C	Any	N/A





**Current Product Version:** Per table below  
**Version Date:** December 2012 (Ver.2)  
**Reference:** 4016

The following issue exists in this version:

**Known Issues:**

- When the PT/TP/WP-57xx products are connected to the VM-114Hxx products and power is connected only to the PT/TP/WP-57xx and turned on, an internal fuse can burn. This requires returning the unit to the factory for repair.

**Workarounds:**

- You must connect the power supply to the VM-114Hxx and power it ON **before** powering ON the PT/TP/WP-57xx.

**Preceding Product Version:** N/A

