

Release Notes

Product Name: RC-43SL

Current Version:

Type	Number	Date
Firmware	4.0.47.53564	June 2019
Software	–	–
Web	–	–
Hardware	–	–

RN Date: June 25, 2019

Reference: 15390

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-43SL	Any	Yes	Yes

Technical Notes:

- Fixed a bug.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: RC-43SL

Current Version:

Type	Number	Date
Firmware	4.0.47.53564	June 2019
Software	–	–
Web	–	–
Hardware	–	–

RN Date: June 25, 2019

Reference: 15390

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
	Fixed an issued that slowed down the device.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
5159	DHCP enabling is not made "on the fly" and requires a 'reset' command afterwards

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
1428	RS-232 Rx: When performing a load RS-232 communication test, one of every thousand characters is lost. Might cause monitoring to fail.
1429	RS-232 Tx: When performing a load RS-232 communication test, one of every thousand characters is lost (Rx+Tx simultaneously). Might cause sending a partial command.
2154	Cannot read/control analog/digital IO (GPIO) on AUX device

Preceding Version: 4.0.45.49251



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: RC-43SL

Current Version:

Type	Number	Date
Firmware	4.0.45.49251	September 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: September 2018

Reference: 14386

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-43SL	Any	Yes	Yes

Technical Notes:

- Added support for Kramer Control.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: RC-43SL

Current Version:

Type	Number	Date
Firmware	4.0.45.49251	September 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: September 2018

Reference: 14386

The following changes were made in this version:

New Features:

	New Feature Description
	Added support for Kramer Control.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
1428	RS-232 Rx: When performing a load RS-232 communication test, one of every thousand characters is lost. Might cause monitoring to fail.
1429	RS-232 Tx: When performing a load RS-232 communication test, one of every thousand characters is lost (Rx+Tx simultaneously). Might cause sending a partial command.
5159	DHCP enabling is not made "on the fly" and requires a 'reset' command afterwards

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
2154	Cannot read/control analog/digital IO (GPIO) on AUX device

Preceding Version: 4.0.43.42085



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: RC-43SL

Current Version:

Type	Number	Date
Firmware	4.0.43.42085	December 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 2017

Reference: 12593

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-43SL	Any	Yes	N/A

Technical Notes:

- Press Release bug was fixed.
- Various bugs were fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: RC-43SL

Current Version:

Type	Number	Date
Firmware	4.0.43.42085	December 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 2017

Reference: 12593

The following changes were made in this version:

Modifications:

QC ID	Modification Description
	Removed unused command descriptions from the Help

Bugs Fixed:

QC ID	Fixed Bug Description
1180	Improper knob behavior over KNET auxiliary keypad.
1991	Web: Allow device web pages to be displayed in IOS and Android platforms
5596	Web: In some cases, when security is enabled, the web page gets ERR 004 for every P3K command, and therefore the page does not come up
8092	Keypad does not reply to ping when using some Cisco switch models in between
10772	The press event doesn't work when using Press-Release Functionality.

Bugs to be Fixed in Future Version:

QC ID	Description
1428	RS-232 Rx: When performing a load RS-232 communication test, one of every thousand characters is lost. Might cause monitoring to fail.
1429	RS-232 Tx: When performing a load RS-232 communication test, one of every thousand characters is lost (Rx+Tx simultaneously). Might cause sending a partial command.
5159	DHCP enabling is not made "on the fly" and requires a 'reset' command afterwards

Known Limitations (including compatibility limitations):

QC ID	Description
-------	-------------



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

2154	Cannot read/control analog/digital IO (GPIO) on AUX device
------	--

Preceding Version: F – 4.0.33.29083



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: RC-43SL

Current Version:

Type	Number	Date
Firmware	4.0.33.29083	July 2016
Software	–	–
Web	–	–
Hardware	U8 - 2458-000017	July 2016

RN Date: August 2016

Reference: 10986

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-43SL	Any	Yes	N/A

Technical Notes:

- Support for new flash component.
- Improved PJLINK protocol handling.

Codependency with Other Products and Software:

There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: RC-43SL

Current Version:

Type	Number	Date
Firmware	4.0.33.29083	July 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: August 2016

Reference: 10986

The following changes were made in this version:

New Features:

	Description
	Support for new flash component
	Improved PJLINK protocol handling

Bugs to be Fixed in Future Version:

QC ID	Description
1180	Improper knob behavior over KNET auxiliary keypad.
1428	RS-232 Rx: When performing a load RS-232 communication test, one of every thousand characters is lost. Might cause monitoring to fail.
1429	RS-232 Tx: When performing a load RS-232 communication test, one of every thousand characters is lost (Rx+Tx simultaneously). Might cause sending a partial command.
1991	Web: Allow device web pages to be displayed in IOS and Android platforms
5159	DHCP enabling is not made "on the fly" and requires a 'reset' command afterwards
5596	Web: In some cases, when security is enabled, the web page gets ERR 004 for every P3K command, and therefore the page does not come up
8092	Keypad does not reply to ping when using some Cisco switch models in between

Known Limitations (including compatibility limitations):

QC ID	Description
2154	Cannot read/control analog/digital IO (GPIO) on AUX device

Preceding Version: F – 4.0.29.24637

Product Name: RC-43SL

Preceding Version: F – 4.0.29.24637

Version Date: February 2016



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Reference: 10064

The following changes were made in this version:

Modifications:

- Support for K-Config 3 features.

QC ID	Description
4956	RC-43SL does not have an "IR on a 3.5mm mini jack connector" control interface
5305	If you press the buttons, they light up. Cannot config the unit without lighting button.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com