

## Release Notes

**Product Name:** TP-789R, TP-789Rxr

**Current Version:**

Type	Number	Date
Firmware	1.31.36.1	January 2018
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** January 21, 2018

**Reference:** 13283

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
TP-789R	N/A	N/A	N/A
TP-789Rxr	N/A	N/A	N/A

### Technical Notes:

- This is a release note for new products.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** TP-789R, TP-789Rxr

**Current Version:**

Type	Number	Date
Firmware	1.31.36.1	January 2018
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** January 21, 2018

**Reference:** 13283

This is a release note for new products. For a list of new product features see:

<http://www.kramerav.com/manual/TP-789Rxr>

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
14475	Up to 150m 1080p extension when connected with TP-780Txr.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
15394	When both extension link end-points are power-supply-connected 2-way POE units, units are not auto-connected during restore from mains power fail. <b>Workaround:</b> Connect only one unit to power-supply, or disconnect and reconnect extension link.

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)