

Release Notes

Product Name: VM-218DT_VM-218DTxr

Current Version:

Type	Number	Date
Firmware	2.4.53633	May 2019
Software	–	–
Web	–	–
Hardware	–	–

RN Date: May 2019

Reference: 15374-15375

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VM-218DT	Any	Yes	Yes
VM-218DTxr	Any	Yes	Yes

Technical Notes:

- Fixed Issues.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: VM-218DT_VM-218DTxr

Current Version:

Type	Number	Date
Firmware	2.4.53633	May 2019
Software	–	–
Web	–	–
Hardware	–	–

RN Date: May 2019

Reference: 15374-15375

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
	Power up and crash issues.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
13941	When Ethernet cable is plugged into the connected HDBT transmitter or receiver, IP access is lost following power cycle. Workarounds: Connect the Ethernet cable directly to VM-218DTxr OR Power cycle the transmitter/receiver.
12985	Upon HDCP enable/disable web-UI change, output AV signal may get lost for 1-2 sec.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
13826	There is no picture when using the SONY Audio Video Control Center.
15704	Web-UI open EDID page may freeze during EDID acquire via panel buttons. Workaround: Close EDID webpage during EDID buttons operations.
15782	Rarely, following power-up, random output may not display signal. Workaround: Plug/replug output cable.

Preceding Version: 2.2.47829



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: VM-218DT_VM-218DTxr

Current Version:

Type	Number	Date
Firmware	2.2.47829	July 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: June 2018

Reference: 12136

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VM-218DT	N/A	N/A	N/A
VM-218DTxr	N/A	N/A	Yes

Technical Notes:

- This is a release note for new products.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: VM-218DT/VM-218DTxr

Current Version:

Type	Number	Date
Firmware	2.2.47829	July 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: June 2018

Reference: 12136

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/VM-218DT>

OR

<http://www.kramerav.com/manual/VM-218DTxr>

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
13941	When the Ethernet cable is connected to the HDBaseT transmitter or receiver that is connected to VM-218DT(xr), VM-218DT(xr) IP access is lost following its power cycle. Workarounds: Connect the Ethernet cable directly to VM-218DTxr OR Power cycle the transmitter/receiver.
12985	HDCP enable/disable change on unselected input causes the displayed video to disappear for 1 second.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com