

Release Notes

Product Name: VM-400HDCPxI

Current Version: Type

Туре	Number	Date
Firmware	6.0.52547	September 2022
Software	_	_
Web	_	_
Hardware	_	_

RN Date: September 4, 2022

Reference: 18349

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VM-400HDCPxI	Any	Yes	Yes

Summary:

- Fixed a bug.
- Added feature(s).
- There is no codependency with other products or software.



Release Notes

Product Name: VM-400HDCPxI

Current Version: Type

Туре	Number	Date
Firmware	6.0.52547	September 2022
Software	_	_
Web	_	_
Hardware	_	_

RN Date: September 4, 2022

Reference: 18349

The following changes were made in this version:

New Features:

New Feature Description
P3K AV-SW-TIMEOUT command: 5-120 sec signal loss timing range.

Modifications:

ID	Modification Description
	Default EDID is updated to 1080p resolution.

Bugs Fixed:

ID	Fixed Bug Description
	No video following EDID read in some AV solutions.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
8584	Problems with turning Force RGB off.
8617	Does not support 14 digit SN.

Preceding Version: 4.0.40281



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com



Product Name: VM-400HDCPxI

Current Version: Type Number Dat

.) 0	T G T T G T T G T G T G T G T G T G T G	
Firmware	4.0.40281	August 2017
Software	_	_
Web	_	_
Hardware	_	_

RN Date: August 2017

Reference: 12309

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VM-400HDCPxI	Any	Yes	N/A

Technical Notes:

• Various bugs were fixed.

Codependency with Other Products and Software:



Product Name: VM-400HDCPxI

Current Version: Type

Туре	Number	Date
Firmware	4.0.40281	August 2017
Software	_	_
Web	_	_
Hardware	_	_

RN Date: August 2017

Reference: 12309

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
8584	Problems with turning Force RGB off
8617	Does not support 14 digits SN
10741	Sometimes, the device gets stuck after copy EDID action
10740	Corrupted EDID in the input after copy
10793	The device gets stuck after running Get EDID when the default EDID is selected
10929	No picture after power ON/OFF on Panasonic monitors
11692	After power up, blinking signal may appear for ~1sec in first connected output

Known Limitations (including compatibility limitations):

None listed.

Preceding Version: FW: 1.0.29540

E-mail: info@kramerav.com
Web: www.kramerav.com



Product Name: VM-400HDCPxI

Current Version: Type Number Date

туре	Number	Date
Firmware	1.0.29540	August 2016
Software	ı	_
Web	1	_
Hardware	1	_

RN Date: September 2016

Reference: 9379

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VM-400HDCPxI	N/A	N/A	N/A

Technical Notes:

• This is a release note for a new product.

Codependency with Other Products and Software:



Product Name: VM-400HDCPxI

Current Version: Type Number Date

туре	Number	Date
Firmware	1.0.29540	August 2016
Software	_	ı
Web	_	ı
Hardware	_	_

RN Date: September 2016

Reference: 9379

This is a release note for a new product. For a list of new product features see: http://www.kramerav.com/manual/VM-400HDCPxI.

Bugs to be Fixed in Future Version:

QC ID	Description
8584	Problems with turning Force RGB off
8617	Does not support 14 digit SN

Known Limitations (including compatibility limitations):

QC ID	Description
8580	Problems with the build-date command

Preceding Version: N/A



Product Name: VM-400HDCPxI

Current Version: Type Number

Type	Nullibei	Date
Firmware	4.0.40281	August 2017
Software	_	_
Web	_	_
Hardware	_	_

RN Date: August 2017

Reference: 12309

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VM-400HDCPxI	Any	Yes	N/A

Technical Notes:

• Various bugs were fixed.

Codependency with Other Products and Software:



Product Name: VM-400HDCPxI

Current Version: Type

Туре	Number	Date
Firmware	4.0.40281	August 2017
Software	_	_
Web	_	_
Hardware	_	_

RN Date: August 2017

Reference: 12309

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
8584	Problems with turning Force RGB off
8617	Does not support 14 digits SN
10741	Sometimes, the device gets stuck after copy EDID action
10740	Corrupted EDID in the input after copy
10793	The device gets stuck after running Get EDID when the default EDID is selected
10929	No picture after power ON/OFF on PANASONIC Monitors
11692	After power up, blinking signal may appear for ~1sec in first connected output

Known Limitations (including compatibility limitations):

• None listed.

Preceding Version: FW: 1.0.29540

E-mail: info@kramerav.com
Web: www.kramerav.com



Product Name: VM-400HDCPxI

Current Version: Type Number Date

туре	Number	Date
Firmware	1.0.29540	August 2016
Software	ı	_
Web	1	_
Hardware	1	_

RN Date: September 2016

Reference: 9379

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VM-400HDCPxI	N/A	N/A	N/A

Technical Notes:

• This is a release note for a new product.

Codependency with Other Products and Software:



Product Name: VM-400HDCPxI

Current Version: Type Number Date

туре	Number	Date
Firmware	1.0.29540	August 2016
Software	_	ı
Web	_	1
Hardware	_	_

RN Date: September 2016

Reference: 9379

This is a release note for a new product. For a list of new product features see: http://www.kramerav.com/manual/VM-400HDCPxI.

Bugs to be Fixed in Future Version:

QC ID	Description
8584	Problems with turning Force RGB off
8617	Does not support 14 digit SN

Known Limitations (including compatibility limitations):

QC ID	Description
8580	Problems with the build-date command

Preceding Version: N/A