



## **Release Notes**

Product Name: VP-429H2

Current Version: Type

Туре	Number	Date
Firmware	0.01.0053	August 2020
Software	1	_
Web	1	_
Hardware	_	_

RN Date: August 9, 2020

Reference: 16616

### **Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-429H2	Any	Yes	Yes

#### **Technical Notes:**

· Fixed a bug.

## **Codependency with Other Products and Software:**





## **Release Notes**

Product Name: VP-429H2

Current Version: Type

Туре	Number	Date
Firmware	0.01.0053	August 2020
Software	_	_
Web	_	_
Hardware	_	_

RN Date: August 9, 2020

Reference: 16616

## **Bugs Fixed:**

QC ID	Fixed Bug Description
18234	Disabling the Authentication no longer causes embedded web pages to crash.

## **Bugs to Fix in Future Versions:**

QC ID	Deferred Bug Description
15554	On input loss after long periods of operation, the output may shut down without delaying according to the configured timeout periods.
18226	Sometimes there are issues loading the EDID Management webpage using 32 bit Internet Explorer.

## **Known Limitations (including compatibility limitations):**

QC ID	Limitation Description
	None listed

Preceding Version: 0.01.0051



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>





Product Name: VP-429H2

Current Version: Type

Туре	Number	Date
Firmware	0.01.0051	December 2019
Software	ı	_
Web	1.4.8	December 2019
Hardware	_	_

RN Date: December 18, 2019

Reference: 15673

#### **Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-429H2	Any	Yes	Yes

#### **Technical Notes:**

- Added values to Protocol 3000 command.
- Improvements in default EDID values.

## **Codependency with Other Products and Software:**





Product Name: VP-429H2

Current Version: Type

Туре	Number	Date
Firmware	0.01.0051	December 2019
Software	_	_
Web	1.4.8	December 2019
Hardware	_	_

RN Date: December 18, 2019

Reference: 15673

The following changes were made in this version:

#### **New Features:**

New Feature Description
Added progress bar when updating firmware.
Added 2 default EDIDs on the webpage. To activate: upgrade to the new FW, restore the device to factory settings, and power cycle the device.

### **Modifications:**

QC ID	Modification Description
	AUD-LVL Protocol 3000 command: Added values changing the level incrementally by 1dB and by XdB.  ++ – (increase current value by 1 step);  – (decrease current value by 1 step)
	++X – (increase current value by X steps);X – (decrease current value by X steps)
	Changed default EDID value from VGA to HDMI 10

### **Bugs to Fix in Future Versions:**

QC ID	Deferred Bug Description
15554	On input loss after long periods of operation, the output may shut down without delaying according to the configured timeout periods.

## **Known Limitations (including compatibility limitations):**

QC ID	Limitation Description
	None listed



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>





Preceding Version: 0.01.0047







Product Name: VP-429H2

Current Version: Type

Туре	Number	Date
Firmware	0.01.0047	June 2019
Software	_	_
Web	1.4.2	June 2019
Hardware	_	_

RN Date: June 2019 Reference: 15411

### **Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-429H2	Any	Yes	Yes

#### **Technical Notes:**

• Modifications and bug fixes.

## **Codependency with Other Products and Software:**





Product Name: VP-429H2

Current Version: Type

Туре	Number	Date
Firmware	0.01.0047	June 2019
Software	_	_
Web	1.4.2	June 2019
Hardware	_	_

RN Date: June 2019 Reference: 15411

The following changes were made in this version:

### **Modifications:**

QC ID	Modification Description
	Updated the audio to follow Kramer standard.
	Long press on remote dry contact switch changed to about 10 steps per second.

## **Bugs Fixed:**

QC ID	Fixed Bug Description
	Web page stability was improved.
15346	Web pages: After changing the baud rate for the RS-232 Data Port, the web page does not show the new baud rate value.

### **Bugs to Fix in Future Versions:**

Deferred Bug Description
On input loss after long periods of operation, the output may shut down without delaying according to the configured timeout periods.

## Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: F: 0.01.0043



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>





Product Name: VP-429H2

Current Version: Type Number Date

Firmware 0.01.0043 April 2019

Software – – 
Web – 
Hardware – –

**RN Date:** April 1, 2019

Reference: 13557

#### **Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-429H2	N/A	N/A	N/A

#### **Technical Notes:**

• This is a release note for a new product.

### **Codependency with Other Products and Software:**





Product Name: VP-429H2

Current Version: Type Number Date

туре	Number	Date
Firmware	0.01.0043	April 2019
Software	_	_
Web	_	_
Hardware	_	_

RN Date: April 1, 2019

Reference: 13557

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/VP-429H2

### **Bugs to Fix in Future Versions:**

QC ID	Deferred Bug Description
15346	Web pages: After changing the baud rate for the RS-232 Data Port, the web page does not show the new baud rate value.
15554	On input loss after long periods of operation, the output may shut down without delaying according to the configured timeout periods.

## Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com