

Release Notes

Product Name: VP-451

Current Version:

| Type | Number | Date |
|----------|--------|---------------|
| Firmware | v1.06 | December 2021 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: December 02, 2021

Reference: 17989

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| VP-451 | Any | Yes | Yes |

Summary:

- EOL MCU replaced by available equivalent
- Firmware update supports new MCU

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: VP-451

Current Version:

| Type | Number | Date |
|----------|--------|---------------|
| Firmware | v1.06 | December 2021 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: December 02, 2021

Reference: 17989

Modifications:

| QC ID | Modification Description |
|-------|---|
| | Firmware upgrade Rev 1.06 supports replaced EOL MCU. Note – The new firmware, Rev 1.06, is backwards compatible to support older MCU as well. |

Bugs Fixed:

| QC ID | Fixed Bug Description |
|-------|--|
| 16391 | After resetting resolution to 1080p/XGA, all input LED lights shut off. |
| 16392 | In the OSD, HDMI2 EDID shows an option for OUTPUT B, even though the device only has one output. |
| 16577 | Spelling error in the OSD. |

Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description |
|-------|--|
| 16552 | Sometimes (very rarely) 4K60 from a MacBook Pro is detected as 4K56. |

Known Limitations (including compatibility limitations):

| QC ID | Limitation Description |
|-------|------------------------|
| | None listed |

Preceding Version: 1.05



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: VP-451

Current Version:

| Type | Number | Date |
|----------|--------|------------|
| Firmware | 1.05 | April 2021 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: April 11, 2021

Reference: 17253

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| VP-451 | Any | Yes | Yes |

Technical Notes:

- Changes for production purposes only.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description |
|-------|--|
| 16391 | After resetting resolution to 1080p/XGA, all input LED lights shut off. |
| 16392 | In the OSD, HDMI2 EDID shows an option for OUTPUT B, even though the device only has one output. |
| 16552 | Sometimes (very rarely) 4K60 from a MacBook Pro is detected as 4K56. |
| 16577 | Spelling error in the OSD. |

Known Limitations (including compatibility limitations):

| QC ID | Limitation Description |
|-------|------------------------|
| | None listed |



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Preceding Version: 1.03



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: VP-451

Current Version:

| Type | Number | Date |
|----------|--------|--------------|
| Firmware | 1.03 | January 2020 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: January 6, 2020

Reference: 007267

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| VP-451 | N/A | N/A | N/A |

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: VP-451

Current Version:

| Type | Number | Date |
|----------|--------|--------------|
| Firmware | 1.03 | January 2020 |
| Software | – | – |
| Web | – | – |
| Hardware | – | – |

RN Date: January 6, 2020

Reference: 007267

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/VP-451

Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description |
|-------|--|
| 16391 | After resetting resolution to 1080p/XGA, all input LED lights shut off. |
| 16392 | In the OSD, HDMI2 EDID shows an option for OUTPUT B, even though the device only has one output. |
| 16552 | Sometimes (very rarely) 4K60 from a MacBook Pro is detected as 4K56. |
| 16577 | Spelling error in the OSD. |

Known Limitations (including compatibility limitations):

| QC ID | Limitation Description |
|-------|------------------------|
| | None listed |

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com