

## Release Notes

**Product Name:** VS-211X, WP-211X

**Current Version:**

Type	Number	Date
Firmware	1.2.56889_110520	July 2020
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** July 20, 2020

**Reference:** 07687

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-211X, WP-211X	N/A	N/A	N/A

### Technical Notes:

- This is a release note for a new product.
- Device has been tested with the latest versions of each of the following market popular browsers:

Windows	IE / Edge
	Firefox
	Chrome
	Safari
Android	Chrome
Mac, iOS	Safari

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** VS-211X, WP-211X

**Current Version:**

Type	Number	Date
Firmware	1.2.56889_110520	July 2020
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** July 20, 2020

**Reference:** 07687

This is a release note for a new product. For a list of new product features see:

- [www.kramerav.com/manual/VS-211X](http://www.kramerav.com/manual/VS-211X)
- [www.kramerav.com/manual/WP-211X](http://www.kramerav.com/manual/WP-211X)

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
17908	Following power-up, audio from the inactive HDMI input may play on the audio port for a few seconds, before the audio from the active HDMI input starts playing.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)