



Release Note

Product Name: VS-21DT, VS-21DTP

Current Version: Ver.Type Ver No.

Ver.Type	Ver No.	Date
Firmware	2.0	December 2017
Software	_	_
Web	_	_
Hardware	_	_

RN Date: December 2017

Reference: 5601

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-21DT	N/A	N/A	N/A
VS-21DTP	N/A	N/A	N/A

Technical Notes:

• This is a release note for a new product.

Codependency with Other Products and Software:

There is no codependency with other products or software.





Release Note

Product Name: VS-21DT, VS-21DTP

Current Version: Ver.Type Ver No. Date

vei.iype	Vei 140.	Date
Firmware	2.0	December 2017
Software	_	-
Web	_	1
Hardware	_	_

RN Date: December 2017

Reference: 5601

This is a release note for a new product. For a list of new product features see:

http://www.kramerav.com/manual/VS-21DT

The following changes were made in this version:

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
12670	The device supports HDCP 1.4 and HDCP 2.2, but cannot convert one version to the other.
12718	In last connected mode, if the inputs are connected and the output is reconnected, the device can switch to the wrong input.
12727	Video issue in a specific setup in which VS-21DT/P is connected to TP-590RXr and a Sony AV receiver is connected between TP-590RXr and the sink.
12902	In priority mode, after performing manual override and then power cycle, the output displays the manual input for a second and then switches to the prioritized input.
15394	VS-21DTP – When both extension link end-points are power-supply-connected 2-way POE units, units are not auto-connected during restore from mains power fail. Workaround: Connect only one unit to power-supply, or disconnect and reconnect extension link.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com