Release Notes

Product Name: **KIT-401**

Current Version:

Type	Number	Date
Firmware	3.13.62886	August 2022
Software	–	–
Web	–	–
Hardware	–	–

RN Date: August 30, 2022
Reference: 18389

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KIT-401	Any	Yes	Yes

Summary:

- Fixed a bug.

Codependency with Other Products and Software:

Product Name	Comments
KIT-401T	

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: **KIT-401**

Current Version:

Type	Number	Date
Firmware	3.13.62886	August 2022
Software	–	–
Web	–	–
Hardware	–	–

RN Date: August 30, 2022
Reference: 18389

Bugs Fixed:

ID	Fixed Bug Description
82180	Added P3K command: #AUD-MODE inp_id, mode_id<CR> auto mute mode for audio analog input. Using this command enables canceling of the "automatic audio mute" on outputs when there is no signal on the analog audio input (issue # 00234856 in KIT-401T).

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
18193	When a Source EDID is copied to all Inputs via dragging it with the mouse, it is copied only to 1 Input or not all.

Preceding Version:
KIT-401T: 3.9.59637
KIT-400R: 1.28

Release Notes History

Product Name: **KIT-401**

Current Version:

Type	Number	Date
Firmware	**KIT-401T:** 3.9.59637 **KIT-400R:** 1.28	May 2021 September 2021
Software	–	–
Web	–	–
Hardware	–	–

RN Date: September 29, 2021
Reference: 17736

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KIT-401	Any	Yes	Yes

Technical Notes:

- Added features.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name:	**KIT-401**		
Current Version:	**Type**	**Number**	**Date**
	Firmware	KIT-401T: 3.9.59637 **KIT-400R:** 1.28	May 2021 September 2021
	Software	–	–
	Web	–	–
	Hardware	–	–
RN Date:	September 29, 2021		
Reference:	17736		

New Features:

	New Feature Description
	Relay settings (ON: NO, OFF: NC).
	TOGGLE PIN Trigger selection.
	Echo ON/OFF command.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
19410	Long press of contact-closure volume up/down button drives max/minimum volume level.
17776	KIT-400R: A delay must be inserted between commands when Maestro sends multiple commands.
19411	The option to load an external EDID is missing when using the embedded web pages with MS Edge or MAC Safari browsers on iOS.
18205	On power up, the transmitter outputs audio on its local analog audio output if the remote HDMI was active when powered down.
19254	Safari-Web (IOS) IP and Device Date & Time fields are unreadable.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
18193	When a Source EDID is copied to all Inputs via dragging it with the mouse, it is copied only to 1 Input or not all.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Preceding Version:
KIT-401T: 3.9.59637
KIT-400R: 1.21

Release Notes History

Product Name: **KIT-401**

Current Version:

Type	Number	Date
Firmware	**KIT-401T:** 3.9.59637 **KIT-400R:** 1.21	May 2021
Software	–	–
Web	–	–
Hardware	–	–

RN Date: May 4, 2021
Reference: 08241

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KIT-401	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.
E-mail: info@kramerav.com
Web: www.kramerav.com

Release Notes History

Product Name:	**KIT-401**		
Current Version:	**Type**	**Number**	**Date**
	Firmware	**KIT-401T:** 3.9.59637 **KIT-400R:** 1.21	May 2021
	Software	–	–
	Web	–	–
	Hardware	–	–
RN Date:	May 4, 2021		
Reference:	08241		

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/KIT-401

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
19410	Long press of contact-closure volume up/down button drives max/minimum volume level.
17776	KIT-400R: A delay must be inserted between commands when Maestro sends multiple commands.
19411	The option to load an external EDID is missing when using the embedded web pages with MS Edge or MAC Safari browsers on iOS.
18205	On power up, the transmitter outputs audio on its local analog audio output if the remote HDMI was active when powered down.
19254	Safari-Web (IOS) IP and Device Date & Time fields are unreadable.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
18193	When a Source EDID is copied to all Inputs via dragging it with the mouse, it is copied only to 1 Input or not all.

Preceding Version: N/A

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com