Product Name: MV-6

Current Version: F – 3.10.20995

Version Date: October 2015

Reference: 9425

Release Type:

☒ Firmware   ☐ Software   ☐ Hardware   ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
MV-6	Any	Yes	N/A

Technical Notes:

- The FPGA-MCU protocol was improved.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: MV-6

Current Version: F – 3.10.20995

Version Date: October 2015

Reference: 9425

The following changes were made in this version:

Fixes:

- Layout window distortion with an extra purple square was fixed.
- Unstable ETH network communication was fixed.

Known Issues:

- There are no known issues.

Preceding Version: F – 3.10.9276.FPGA

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: MV-6

Preceding Version: F – 3.10.9276.FPGA

Version Date: August 2013

Reference: 6221

The following changes were made in this version:

Fixes:

- When setting the output resolution to 720p (from 1080p) there is sometimes no picture from the HDMI & SDI outputs.

Known Issues:

- In some cases, changing the IP address and then cycling the device power may result in the IP address reverting to 0.0.0.0 and loss of communication.

  To resolve, reset the device to its factory settings (hold down the RESET button for at least 40 seconds as the device is being powered up) and try again.

Preceding Version: F – 3.10.9276

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: MV-6

Current Version: F – 3.10.9276

Version Date: July 2013

Reference: 6049

The following changes were made in this version:

Fixes:

- Sometimes units don't respond after working 30 - 40 minutes.

Known Issues:

- There are no known issues.

Preceding Version: F – 3.2.7321

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Preceding Version: 3.2.7321

Version Date: December 2012

Reference: 4625

The following changes were made in this version:

Added Features:

- A text overlay feature was added.

Fixes:

- The model name in the software application did not reset to the factory default after performing a factory reset.
- The front panel did not lock on receiving a locking command.
- When using the MV-6 PC application, moving or resizing windows distorted the colors.

Known Issues:

- There are no known issues.

Preceding Firmware Version: N/A

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com
Web: www.kramerelectronics.com