Release Notes

Product Name: **VP-440X**

Current Version:

Type	Number	Date
Firmware	1.18	July 2024
Software	–	–
Web	–	–
Hardware	–	–

RN Date: July 22, 2024
Reference: 019716

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-440X	Any	Yes	Yes

Summary:

- The embedded web pages were re-branded with a new logo and loading icon.
- The embedded web pages About information was updated.

Codependency with Other Products and Software:

Product Name	Comments

- There is no codependency with other products or software.

Modifications:

QC ID	Modification Description
	The embedded web pages were re-branded with a new logo and loading icon.
	The embedded web pages About information was updated.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Release Notes

Product Name: **VP-440X**

Current Version:

Type	Number	Date
Firmware	1.18	July 2024
Software	–	–
Web	–	–
Hardware	–	–

RN Date: July 22, 2024
Reference: 019716

Preceding Version: 1.17

Release Notes History

Product Name: **VP-440X**

Current Version:

Type	Number	Date
Firmware	1.17	September 2022
Software	–	–
Web	–	–
Hardware	–	–

RN Date: September 5, 2022
Reference: 18440

New Features:

	New Feature Description
	N-A

Modifications:

QC ID	Modification Description
	An HDCP compatibility issue with the Kramer TP-600T/R was resolved.
CYP-1172	Floating digit numbers are now rounded to the closest integer or half integer value as required by a new DSP chip.

Bugs Fixed:

QC ID	Fixed Bug Description
17243	The front panel's left and right buttons did not change the output volume when not in the OSD menu.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: 1.10

Release Notes History

Product Name: **VP-440X**

Current Version:

Type	Number	Date
Firmware	1.10	April 2020
Software	–	–
Web	–	–
Hardware	–	–

RN Date: April 5, 2020

Reference: 07438

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-440X	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: **VP-440X**

Current Version:

Type	Number	Date
Firmware	1.10	April 2020
Software	–	–
Web	–	–
Hardware	–	–

RN Date: April 5, 2020
Reference: 07438

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/VP-440X

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	Some issues with echoed DSP mic values.
16586	When an input signal is detected after the unit has automatically shut the outputs down, a CEC ON command is not sent to the HDBT output.
17168	The "name" on the Device Settings webpage does not revert to its default value after performing a factory reset.
17195	RS-232 commands added to the "External Device commands configuration" are not included in a saved configuration file.
17198	There is no echoing on the serial port when changes are made to parameters on the Output Settings webpage.
17225	Cannot set floating point numbers for the audio equalization in the audio webpage.
17243	Left and right buttons do not change the output volume when not in the OSD menu.
17309	Issues accessing the device via Internet Explorer.
17325	Issues with uploading EDID files via the USB port.
17872	The R, G, B setting may not be edited as text via the web.
17882	CEC bypass does not work when Auto-Sync Off is enabled.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: N/A

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com