KRAMER

Release Note

Product Name: VS-62DT

Current Version:

Ver.Type	Ver No.	Date
Firmware	1.5.37030	May 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: **May 2017**

Reference: **12376**

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-62DT	Any	Yes	N/A

Technical Notes:

- Firmware for new Flash memory.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER

Release Note History

Product Name: VS-62DT

Current Version:

Ver.Type	Ver No.	Date
Firmware	1.5.37030	May 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: May 2017

Reference: 12376

The following changes were made in this version:

New Features:

New Feature Description
Firmware for new Flash memory

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
9534	The device IP address didn't change after switching DHCP from on to off
9618	Product doesn't support reading of Valence FW version

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: F - 1.5.32829

Release Note History

Product Name: VS-62DT

Preceding Version:

Ver.Type	Ver No.	Date
Firmware	1.5.32829	December 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: February 2016

Reference: 10060

This is a release note for a new product. For a list of new product features see:

http://www.kramerav.com/downloads/VS-62DT

Bugs to be Fixed in Future Version:

QC ID	Description
9534	The device IP address didn't change after switching DHCP from on to off
9618	Product doesn't support reading of Valence FW version

Known Limitations (including compatibility limitations):

QC ID	Description
	None listed

Preceding Version: N/A