Release Notes

Product Name: **WP-20CT**

Current Version:

Type	Number	Date
Firmware	1.0.64658	October 23
Software	–	–
Web		
Hardware	–	–

RN Date: October 29, 2023
Reference: 019273

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
WP-20CT	Any	Yes	Yes

Summary:

- Updated brand.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Modifications:

Issue ID	Modification Description
	New Karmer logo appearance.

Bugs Fixes:

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: **WP-20CT**

Current Version:

Type	Number	Date
Firmware	1.0.64658	October 23
Software	–	–
Web		
Hardware	–	–

RN Date: October 29, 2023
Reference: 019273

Modifications:

ID	Modification Description
	New Kramer logo appearance.

Bugs Fixes:

ID	Deferred Bug Description
84916	Occasional flickering video output when using USB-C input.
82672	Active ROUTE command after cycle.
82676	Serial baud rate web-UI selection and storage.

Known Limitations (including compatibility limitations):

N/A

Preceding Version: WP-20CT_1.0.62581_2022_3_2

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name:	**WP-20CT**		
Current Version:	**Type**	**Number**	**Date**
	Firmware	1.0.62581	July 2022
	Software	–	–
	Web	1.0.14	– July 2022
	Hardware	–	–

RN Date:	**July 2022**
Reference:	**V1.0.62581, 1.0.1.4**

Kramer Product Affected:

Product Name	**Minimum FW Version for Upgrade**	**Recommended for All Units**	**Only if Added Features are Required**
WP-20CT	Any	Yes	N/A

Codependency with Other Products and Software:

- There is no codependency with other products or software.

Bugs Fixes:

ID	**Deferred Bug Description**
81156	WP-20CT works at HDCP Follow Input although it is set at web to Follow Output.

There is no preceding version.