

## Release Notes

**Product Name:** ASPEN-1616UX

**Current Version:**

Type	Number	Date
Firmware	01.01.0004	December 2018
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** December 30, 2018

**Reference:** 13229

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
ASPEN-1616UX	N/A	N/A	N/A

### Technical Notes:

- This is a release note for a new product.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** ASPEN-1616UX

**Current Version:**

Type	Number	Date
Firmware	01.01.0004	December 2018
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** December 30, 2018

**Reference:** 13229

This is a release note for a new product. For a list of new product features see:

[www.kramerav.com/manual/ASPEN-1616UX](http://www.kramerav.com/manual/ASPEN-1616UX)

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
13802	P3K NET-DHCP command with the paramer 0 does not return an error message
13819	P3K NET-CONFIG command provids in addition to the p[rotocol expected IP, Net-mask and Gateway also DNS1 and DNS2 parametrs
13821	WEB pages browsing with Ipad Safari V10 or lower is possible by disabling the 'Private Mode' browsing
14469, 14471	Web pages: Minor design improvements.
14506	Web pages: Use F11 to toggle Full screen display. The full screen exit button, may not work in some versions of Chrome Web browser.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)