



Release Notes

Product Name: FC-102NET

Current Version: Type

Туре	Number	Date
Firmware	R1.1.61051_08072021	August 2021
Software	_	_
Web	_	_
Hardware	_	_

RN Date: August 22, 2021

Reference: 17714

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
FC-102NET	Any	Yes	Yes

Technical Notes:

• Fixed a bug.

Codependency with Other Products and Software:

• There is no codependency with other products or software.





Release Notes

Product Name: FC-102NET

Current Version: Type

Туре	Number	Date
Firmware	R1.1.61051_08072021	August 2021
Software	_	_
Web	_	_
Hardware	_	_

RN Date: August 22, 2021

Reference: 17714

Bugs Fixed:

QC ID	Fixed Bug Description
	Fixed issue of noise gate and DC on input.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
13709	After a performing a factory reset, the IP address on the Dante Controller is not aligned with the device IP.
	Workaround: Reset the Dante Controller in one of the following ways:
	Reset the device through the Dante Controller.
	Disconnect the power source of the device – the RJ-45 connector.

Preceding Version: 1.1.51742



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>





Release Notes History

Product Name: FC-102NET

Current Version: Type

Туре	Number	Date
Firmware	1.1.51742	March 2019
Software	_	_
Web	_	_
Hardware	_	_

RN Date: March 7, 2019

Reference: 13513

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
FC-102NET	N/A	N/A	N/A

Technical Notes:

This is a release note for a new product.

Codependency with Other Products and Software:

There is no codependency with other products or software.





Release Notes History

Product Name: FC-102Net

Current Version: Type

Туре	Number	Date
Firmware	1.1.51742	March 2019
Software	_	_
Web	_	_
Hardware	_	_

RN Date: March 7, 2019

Reference: 13513

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/FC-102Net

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
13709	After a performing a factory reset, the IP address on the Dante Controller is not aligned with the device IP.
	Workaround: Reset the Dante Controller in one of the following ways:
	Reset the device through the Dante Controller.
	Disconnect the power source of the device – the RJ-45 connector.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com