



**Product Name:** FC-28  
**Current Version:** NP – 1.0  
**Version Date:** March 2016  
**Reference:** 8491

**Release Type:**

Firmware       Software       Hardware       New Product

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
FC-28	N/A	N/A	N/A

**Technical Notes:**

- This is a release note for a new product.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerel.com](mailto:info@kramerel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** FC-28  
**Current Version:** NP – 1.0  
**Version Date:** March 2016  
**Reference:** 8491

This is a release note for a new product.

### Known Issues:

- Incorrect GPIO digital output state-change report to clients
- GPIO analog input steps start from 0, not from 1
- Incorrect GPIO analog input step-change value report to clients
- Relay state feedback message has extra space

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)