

Product Name:	KDock-5 Systems		
Current Version:	Туре	Number	Date
	Firmware	R10577	May 2024
	Software		_
	Web		_
	Hardware		_
RN Date:	May 2024		
Reference:	019701		

#### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KDock-5	Any	Yes	Yes

#### Summary:

• Fixed a bug.

### **Codependency with Other Products and Software:**

Product Name	Comments
CA-U32/FF	All configurations (long cables)
CLS-AOCU32/FF	All configurations (long cables)
While working used should be	with long USB C cables, over 10feet, the external power supply e no higher than 65W.





Product Name:	KDock-5 Systems		
Current Version:	Туре	Number	Date
	Firmware	R10577	May 2024
	Software		_
	Web		_
	Hardware		_
RN Date:	May 2024		
Reference:	019701		

### Bugs Fixed:

ID	Fixed Bug Description
	KDock-5 is now compatible with USB-C long cables.
	Note: Follow instructions in Software Upgrade: section.

### Software Upgrade:

Pre-requisite:

• On a computer running Windows, turn OFF the Anti-virus program.

Installing the SW:

1. Go to the KDock-5 Product page>Resources tab on the Kramer website and double-click the upgrade installation tool.

The Setup dialog box opens.





2. Click Confirm.



The Setup - VLI Hub PD FW Upgrade Tool screen opens.

3. Click Next.



4. Click Next.





KRAMER ELECTRONICS, Ltd. E-mail: info@kramerav.com Web: www.kramerav.com



### 5. Click Next.

🙀 Setup - VLI Hub PD FW Upgrade Tool	—	
Select Additional Tasks Which additional tasks should be performed?		
Select the additional tasks you would like Setup to perform while in: FW Upgrade Tool, then dick Next.	stalling VL	I Hub PD
Additional icons:		
☑ Create a desktop icon		
1977 - Xerryan Baler, Sandalan Banara, 2017 - 1		
< Back Ne	xt >	Cancel

6. Click Install.







7. Click Finish.



The upgrade software installation is complete.

### Upgrading the FW

1. On the desktop, double-click the VLIHubPD FW icon.



2. Using the device's USBC TO USBC line, connect the device to the computer and wait for 2-3 seconds.



0		Scan Device	Upgrade FW
2 Devic	es found:		4
Device(	1): Depth0, V/PII	$D = 2109/0817(Q7_C0), F'$	W Ver = $06F4$
PD-Dev	nce: $V/PID = 210$	19/0103, FW Ver = 0A.01.0	1.//

The icon is displayed in green, and the dialog box shows the product version number.





### 4. Click Upgrade FW.

The tool starts upgrading the device.

5. Once the progress bar is complete, click **OK**.



The upgrade is completed.

Preceding Version: N/A

