

## Release Notes

**Product Name:** MTX2-42-T

**Current Version:**

Type	Number	Date
Firmware	V1.01	June 2024
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 19, 2024

**Reference:**

### Summary:

- This is a new product release.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** MTX2-42-T

**Current Version:**

Type	Number	Date
Firmware	V1.01	May 2024
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 19, 2024

**Reference:**

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/Product>

### Know Limitations

ID	Description
3596	When Ethernet cable is connected during factory reset & no DHCP server is detected, fallback IP address is not activated. Workaround: Unplug & re-plug Ethernet cable.

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)