

Release Notes

Product Name: MV-4X

Current Version:

Type	Number	Date
Firmware	1.08	February 2023
Software	–	–
Web	–	–
Hardware	–	–

RN Date: February 8, 2023

Reference: 18462

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
MV-4X	Any	Yes	Yes

Summary:

- Fixed a bug.
- Added feature(s).

Codependency with Other Products and Software:

Product Name	Comments

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: MV-4X

Current Version:

Type	Number	Date
Firmware	1.08	February 2023
Software	–	–
Web	–	–
Hardware	–	–

RN Date: February 8, 2023

Reference: 18462

Bugs Fixed:

QC ID	Fixed Bug Description
	When cycling power, sometimes a 6G picture was not shown
3487	The video pixel parameters differed for each HDMI input
3419	Default contrast level was too low.
	When upgrading firmware by webpage, MV-4X sometimes got stuck.
3516	Kramer logo was unclear.
3517	"Are You sure change timing?" message changed to Press enter to confirm new resolution when pressing revert to XGA button.
3519	Security lock icon updates correctly when working with more than one web page.
3520	Fixed bug for device exiting standby in QUAD mode.
3521	Menu transparency feature works in the web page.
3522	Exit full screen button is now functional.
3523	Kramer web page updated.
3526	Fixed bug for Fade In & Out operation.
3527	The black line "Rotate > Off works properly when resetting window layout.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
3524	Wrong ERR code: Some P3K commands show ERR 002 even when that Command exists.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
3339	Firmware upgrading should be done via the web interface or via USB, not via KUpload. (KUpload is far too slow for practical use).
868	The resolution is not determined at the HDBT output if set to output resolution 3840x2400RB

Preceding Version: 1.04



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: MV-4X

Current Version:

Type	Number	Date
Firmware	1.04	March 2022
Software	–	–
Web	–	–
Hardware	–	–

RN Date: June 20, 2022

Reference: 8787

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
MV-4X	N/A	N/A	N/A

Summary:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: Product

Current Version:

Type	Number	Date
Firmware	1.04	March 2022
Software	–	–
Web	–	–
Hardware	–	–

RN Date: June 20, 2022

Reference: 8787

Known Bugs and Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
-	-

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
3339	Firmware upgrading should be done via the web interface or via USB, not via KUpload. (KUpload is far too slow for practical use).
868	The resolution is not determined at the HDBT output if set to output resolution 3840x2400RB

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com