
Installation and Assembly - Adapter Bracket for VESA® 400 x 400 Screens

IMPORTANT! Read instruction sheet before you start installation and assembly.

Before you start make sure all parts listed are included with your product.




AWARNING

Do not overtighten. Overtightening may cause permanent damage to the screen. Torque to 26-35 in • lb (30-40 kg • cm).

Using 5/32" (4mm) security allen wrench (FF), attach adapter plate (AA) to screen using either four M8 x 15 mm screws (DD) or four M6 x 12 mm serrated washer head socket pin screws (CC) and four 1/4" flat washers (EE).

NOTE: Screw must make at least three full turns into the mounting hole and fit snug into place. If you have any questions, please call Peerless customer care at 1-800-865-2112.



ISSUED: 03-18-08 SHEET #: 202-9277-2 07-10-08 For customer care call 1-800-729-0307 or 708-865-8870.

Visit the Peerless Web Site at www.peerlessmounts.com

1 of 1