

## Release Notes

**Product Name:** PT-872xr

Current Version:	Ver.Type	Ver No.	Date
	Firmware	–	–
	Software	–	–
	Web	–	–
	Hardware	–	–

**RN Date:** March 2018

**Reference:** 12825

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
PT-872xr	N/A	N/A	N/A

### Technical Notes:

- This is a release note for a new product.
- Limitation: Source and display AV signal compatibility must adhere to EDID parameters. Incompatibility may cause signal delivery failures, such as audio noise payout.

### Codependency with Other Products and Software:

Product Name	Comments
WP-871xr	Compatible wall-plate receiver



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note History

**Product Name:** PT-872xr

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	–	–
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** March 2018

**Reference:** 12825

This is a release note for a new product. For a list of new product features see:

[www.kramerav.com/manual/PT-872xr](http://www.kramerav.com/manual/PT-872xr)

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	For specified extension distance performance, use Kramer DGKat cables with no mid-span cable connections.
	Use only shielded cable with both ends of the shield soldered to ground to eliminate ESD interface and with no mid-span cable connections.

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)