

















A	B	C	D	E	F	G	H	I	J	K	L	M	N	O
														
1	1	1	2	4 M5*20	4 M6*12	4	2	8 M4*9	1 #3 (3mm)	1 #4 (4mm)	1 #5 (5mm)	2 Option	4	4 M5*7



1 Insert bar A into base B. Attach bar J to the base.

2 Attach bar C to the base.

3 Attach bar C to the vertical bar A.

4 Attach bar C to the vertical bar A.

5 Attach screw F to bar C.

6 Attach bar C to the vertical bar A.

7 Attach bar C to the vertical bar A.

8 Attach bar C to the vertical bar A.

9 Attach bar C to the vertical bar A.

10 Attach bar C to the vertical bar A.

11 Attach bar C to the vertical bar A.

12 Attach bar C to the vertical bar A.

13 Attach bar C to the vertical bar A.

14 Attach bar C to the vertical bar A.

15 Attach bar C to the vertical bar A.

16 Attach bar C to the vertical bar A.

17 Unlocked position.

18 Locked position.