

# **Release Notes**

# Product Name:

#### SWT3-21-H. SWT3-41-H

Current '	Version:

34413-21-11, 34413-41-11			
Туре	Number	Date	
Firmware	Ver. 1.0.64863	November 2023	
Software	—	_	
Web	—	—	
Hardware	—	—	

RN Date: Reference:

#### November 30, 2023

## **Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SWT3-21-H, SWT3-41-H	N/A	N/A	N/A

#### Summary:

This is a release note for a new product. •

#### **Codependency with Other Products and Software:**

• There is no codependency with other products or software.

#### **Replaced Products:**

N/A





# **Release Notes**

Product Name: Current Version:

#### SWT3-21-H, SWT3-41-H

:	Туре	Number
	Firmware	Ver. 1.0.64863
	Software	_

\_

\_

Date

\_

\_

\_

November 2023

RN Date:		
	RN Date:	

November 30, 2023

Reference:

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/SWT3-21-H, SWT3-41-H

Web

Hardware

#### Bugs to Fix in Future Versions:

ID	Deferred Bug Description	
1557	Panel audio buttons operation is reflected wrongly on web-UI audio views	
1562	Few NET LED indications are wrong	
	Detected buttons click is longer than standard	

## Known Limitations (including compatibility limitations):

None listed

Preceding Version: N/A

