

# **Release Notes**

Product Name:	VIA 4.1.0.1422 (patch)		
<b>Current Version:</b>	Туре	Number	Date
	Firmware	4.1.0.1422	July 25, 2024
	Software	_	-
	Web	-	-
	Hardware	_	-
RN Date:	July 25, 2024		
Reference:	019782		

### Kramer Products Affected:

Product Name	Minimum FW version for upgrade	Recommended for all units	Only if the new features are required
VIA Go <sup>2</sup>	4.1.0.1417	No	Yes
VIA Connect <sup>2</sup>	4.1.0.1417	No	Yes
VIA Campus <sup>2</sup>	4.1.0.1417	No	Yes
VIA Campus <sup>2</sup> Plus	4.1.0.1417	No	Yes

#### Summary:

- VIA 4.1 availability.
- Added features

### Availability:

	Comments
VIA Gateway	VIA 4.1 now available for VIA Pad.

#### **New Features:**

Product Name	Comments
VIA Gateway	@ character support added for Active Directory.

## **Codependency with Other Products and Software:**

Product Name	Comments
VIA Client	Use of this firmware requires installation of the VIA Client (room device driver) version 1.0.27 or higher.





# **Release Notes**

Product Name:	VIA 4.1.0.1422 (patch)		
<b>Current Version:</b>	Туре	Number	Date
	Firmware	4.1.0.1422	July 25, 2024
	Software	-	-
	Web	-	_
	Hardware	-	_
RN Date:	July 25, 2024		
Reference:	019782		

This is a release note for a new product. For a list of new product features see:

http://www.kramerav.com/manual/Product

## **Bugs to Fix in Future Versions:**

ID	Deferred bug description
	None listed

### Known Limitations (including compatibility limitations):

ID	Limitation description
	None listed

#### Preceding Version: 4.1.0.1417





# **Release Notes History**

Product Name:	VIA 4.1		
<b>Current Version:</b>	Туре	Number	Date
	Firmware	4.1.01417	April 22, 2024
	Software	-	_
	Web	-	_
	Hardware	-	_
RN Date:	June 03, 2024		
Reference:	019680		

#### **Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VIA Go <sup>2</sup>	3.3.0722.1240	Yes	No
VIA Connect <sup>2</sup>	3.3.0722.1240	Yes	No
VIA Campus <sup>2</sup>	3.3.0722.1240	Yes	No
VIA Campus <sup>2</sup> Plus	3.3.0722.1240	Yes	No

#### Summary:

Fixed bugs.

Added features.

#### **Bug Fixes:**

Jira No.	Comments
VG-6493	Presentation of MAC Client is not working through MacOS Sonoma (version 14) Fixed
	Cursor shape change at the time of Window resizing (for Connect2 and Go2) – Fixed.
	When presenting 4K display, the cursor is getting bigger and consumes memory. Also, at times this is causing the Gateway to crash. – Fixed.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com Web: www.kramerav.com



# **Release Notes History**

VG-2970	MAC via Client > VIA Info > version should appear instead of 'Created by Qt/QMake' Fixed
VG-5476	VSM On Prem/VIA Go2: VSM server and the gateways have been updated. Character limit for Room name. – Fixed.
VG-5821	VIA is unable to recognize Biamp-Parle 2500 sound bar Fixed
VG-3747	If we join through browser > sleep mode > gateway does not go in sleep mode after logging out or closing the tab of Chrome client Fixed
VG-6245	Multicast functionality stops working after 30 minutes in Connect2 Fixed
VG-5771, VG-5967	VIA Android application crash Fixed
VG-6062	VIA App version 4.0.1.1328/ 4.0.3.1340 Beta, not identify custom room name from Connect Plus.

#### **New Features:**

Product Name	Comments
	Wi-Fi direct (VIA Connect2 and VIA Go2 only)
	Camera Switching (VIA Campus2, VIA Campus2Plus, VIA Connect2 only)

#### **Enhancements:**

Product Name	Comments
	Supports Ubuntu 22 (VIA Connect2, VIA Go2) – for reimage only.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com Web: www.kramerav.com