

## Release Note

**Product Name:** VM-2D

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	4.0.41739	November 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** November 2017

**Reference:** 11239

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VM-2D	N/A	N/A	N/A

**Technical Notes:**

- This is a release note for a new product.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note

**Product Name:** VM-2D

<b>Current Version:</b>	Ver.Type	Ver No.	Date
	Firmware	4.0.41739	November 2017
	Software	–	–
	Web	–	–
	Hardware	–	–

**RN Date:** November 2017

**Reference:** 11239

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/VM-2D>

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
12243	Incorrect Get result for #av-sw-timeout? Protocol 3000 command

### Known Limitations (including compatibility limitations):

- None listed.

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)