

## Release Notes

**Product Name:** VP-554x

**Current Version:**

Type	Number	Date
Firmware	2.43	January 2023
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** January 25, 2023

**Reference:** 18644

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-554x	Any	Yes	Yes

### Summary:

- Added new feature.

### New Features

	New Feature Description
	RS-232 Routing/Port Tunneling is enabled

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
11152	Some commands executed via OSD are not echoed via P3K

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
1588	If the OSD SELECT button is pressed when an OSD menu is open, the OSD menu remains open in the previous window

**Preceding Version:** 2.42



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** VP-554x

**Current Version:**

Type	Number	Date
Firmware	2.42	February 2022
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 20, 2022

**Reference:** 8774

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-554X	N/A	N/A	N/A

### Summary:

- This is a release note for a new product.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** Product

**Current Version:**

Type	Number	Date
Firmware	2.42	February 2022
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 20, 2022

**Reference:** 8774

### Known Bugs and Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
11152	Some commands executed via OSD are not echoed via P3K

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
1588	If the OSD SELECT button is pressed when an OSD menu is open, the OSD menu remains open in the previous window

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)