

Release Notes

Product Name: WP-SW2-EN7

Current Version:

Type	Number	Date
Firmware	1.0.10	April 2024
Software	–	–
Web	–	–
Hardware	–	–

RN Date: April 1, 2024

Reference: 19043

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
WP-SW2-EN7	Any	Yes	Yes

Summary:

- Fixed bugs.
- Added feature(s).

Codependency with Other Products and Software:

Product Name	Comments

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: WP-SW2-EN7

Current Version:

Type	Number	Date
Firmware	1.0.10	April 2024
Software	–	–
Web	–	–
Hardware	–	–

RN Date: April 1, 2024

Reference: 19043

New Features:

	New Feature Description
GB-821	Added new Kramer Web-UI elements including new logo, address, splash image etc.
	Added feature change AES128 encryption key.
GB-1053	Added the option to lower the Baud rate to 1200 and 2400.
	Added the option to change the Multicast IP prefix.
	Added daylight saving time with start/end date range configuration.
	Added 802.1X support on Service Port.
	Added 802.1X status on Web-UI.

Modifications:

ID	Modification Description
	Changed the CEC control on Web-UI with dropdown and SEND button.

Dropped Features:

	Dropped Feature Description

Bugs Fixed:

ID	Fixed Bug Description
GB-1028	No validation for Unique Channel ID automatic assignment.
GB-880	UDP connection is not reflected on Status → Connections.
GB-782	EAP-TLS: no validation for wrong Private Key.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

ID	Fixed Bug Description
GB-781	EAP-TLS: no validation for inserting invalid client certificate file.
GB-847	The list returned by #SIGNALS-LIST includes only the active input.
GB-809	Getting gateway messages by using GTW-MSG-NUM doesn't filter messages by dates and displays all messages.
GB-765	When setting Syslog to OFF, file status displays 'log is open'.

Bugs to Fix in Future Versions:

ID	Deferred Bug Description
GB-866	After powering up the unit, the LCD and WEB display work slowly during the first 2 minutes.

Known Limitations (including compatibility limitations):

ID	Limitation Description
	None listed

Preceding Version: 0.8.6



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: WP-SW2-EN7

Current Version:

Type	Number	Date
Firmware	0.8.6	June 2022
Software	–	–
Web	–	–
Hardware	–	–

RN Date: June 2022

Reference: 60-000990

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
WP-SW2-EN7	N/A	N/A	N/A

Summary:

- This is a release note for a new product.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: KDS-SW2-EN7

Current Version:

Type	Number	Date
Firmware	0.8.6	June 2022
Software	–	–
Web	–	–
Hardware	–	–

RN Date: June 2022

Reference: 60-000990

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/KDS-SW2-EN7

Bugs to Fix in Future Versions:

ID	Deferred Bug Description
GB-866	After powering up the unit, the LCD and WEB display work slowly during the first 2 minutes.
GB-847	The list returned by #SIGNALS-LIST includes only the active input.
GB-809	Getting gateway messages by using GTW-MSG-NUM doesn't filter messages by dates and displays all messages.
GB-821	Need to update the new Kramer address in the About page.
GB-765	When setting Syslog to OFF, file status displays 'log is open'.

Known Limitations (including compatibility limitations):

ID	Limitation Description
	None listed

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: WP-SW2-EN7

Current Version:

Type	Number	Date
Firmware	0.11.12	January 2023
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 31, 2023

Reference: 18696

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
WP-SW2-EN7	N/A	N/A	N/A

Summary:

- Fixed a bug.
- Added feature(s).

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: WP-SW2-EN7

Current Version:

Type	Number	Date
Firmware	0.11.12	January 2023
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 31, 2023

Reference: 18696

Bugs to Fix in Future Versions:

	Deferred Bug Description
	None listed

Known Limitations (including compatibility limitations):

	Limitation Description
	None listed

Preceding Version: 0.8.6



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com