
User Manual


427-CS08



Desk Spacer, + 65 mm

In order to achieve a correct mounting of LiftSystem Track, you are advised to read and follow the instructions step by step. If there are incomprehensible steps, please let us know and we will get back to you.

Part Check-List




(2



х8


1 Start by removing the cover of the LiftSystem Track. Put the cover aside.



2 Examine the illustration below and proceed with the removal of the LiftSystem Track springed pin. Remove in two steps:



2 Direct outwards away from the hole.




- www.kondator.se

Assembly Guide


3 Assembly the LiftSystem Track with the corresponding hooks from the Desk Spacer(1).




1 Align and insert into holes.




3 Ascertain its position.



4 Mount assembly to table using all wood screws 2.



5 Insert intended sleighmodule into the track.



6 Re-attach the springed-pin and the cover.





