



Release Notes

Product Name: FC-101NET

Current Version: Ve

Ver.Type	Ver No.	Date
Firmware	1.1.47355	June 2018
Software	_	_
Web	_	_
Hardware	_	_

RN Date: June 2018

Reference: 12396

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
FC-101NET	N/A	N/A	N/A

Technical Notes:

• This is a release note for a new product.

Codependency with Other Products and Software:

• There is no codependency with other products or software.





Release Notes

Product Name: FC-101NET

Current Version: Ver.Type Ver No. Date

ver.Type	ver no.	Date
Firmware	1.1.47355	June 2018
Software	1	_
Web	1	_
Hardware	_	_

RN Date: June 2018

Reference: 12396

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/FC-101NET

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description	
	The default IP setting is DHCP. Performing a factory reset sets the unit to static IP: 192.168.1.39, normally Dante devices are set to DHCP.	
13709	After a performing a factory reset, the IP address on the Dante Controller is not aligned with the device IP.	
	Workaround: Reset the Dante Controller in one of the following ways:	
	 Reset the device through the Dante Controller. 	
	 Disconnect the power source of the device – the RJ-45 connector. 	

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com