

## Release Notes

**Product Name:** KDS-8-MNGR

**Current Version:**

Type	Number	Date
Firmware	3.2	October 2024
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** October 15, 2024

**Reference:** 019760

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KDS-8-MNGR	N-A	N-A	N-A

### Bug Fix:

	Description
CYP-3598	KDS-8-MNGR locks up when the input resolution is 1280x1024.

**Preceding Version:** – 3.17



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** KDS-8-MNGR

**Current Version:**

Type	Number	Date
Firmware	3.17	May 2022
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** May 11, 2022

**Reference:** 18189

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KDS-8-MNGR	N/A	N/A	N/A

### New Features:

	New Feature Description
Telnet Command	Added the following telnet command: set multiview preset n1 source s1 id n2 (set one specific source in the layout of a multi-view preset) For example, set multiview preset 1 source F8:22:85:00:00:02 id 3 To execute the preset, set multiview preset 1.

### Technical Notes:

- This is a release note for a new product.

### Codependency with Other Products and Software:

Product Name	Comments
KDS-8	
KDS-8F	

This is a release note for a new product. For a list of new product features see:

[www.kramerav.com/manual/KDS-8-MNGR](http://www.kramerav.com/manual/KDS-8-MNGR)

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
19338	Degraded picture quality when using the 2 Multiview preset.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Current Version:**

Type	Number	Date
Firmware	3.17	May 2022
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** May 11, 2022

**Reference:** 18189

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed
Product Name:	KDS-8-MNGR

**Preceding Version:** 3.11



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** KDS-8-MNGR

**Current Version:**

Type	Number	Date
Firmware	3.11	August 2021
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** July 11, 2021

**Reference:** 08420

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KDS-8-MNGR	N/A	N/A	N/A

This is a release note for a new product. For a list of new product features see:

[www.kramerav.com/manual/KDS-8-MNGR](http://www.kramerav.com/manual/KDS-8-MNGR)

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
19338	Degraded picture quality when using the 2 Multiview preset.
19361	After changing the scaling resolution from the decoder (receiver) side, the resolution returns to the original setting after stopping and starting streaming.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)