

Release Notes History

Product Name: KT-20x Touch Panels

Current Version:

| Type | Number | Date |
|----------|---------|--------------|
| Firmware | 1.11.38 | January 2023 |
| Hardware | - | — |

RN Date: January 2023

Reference: 019423

Kramer Product Affected:

| Product Name | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|--------------|--------------------------------|---------------------------|-------------------------------------|
| KT-205WM | Any | Yes | Yes |
| KT-208 | Any | Yes | No |
| KT-2010 | Any | Yes | No |

Summary:

- Critical pages now initialize correctly, ensuring all reset capabilities are functioning.
- Updated Kramer Flex to V14
- Default Screen dimming timeout was changed to 15s.
- Added Model names for upcoming touch panels.
- Incorporated K-Agent version 1.0.62
- Updated Android security patch to 2023-09-01
- Updated factory test app to V1.9
- Disabled quick settings in Launcher and other unused features.
- Added SOC SN info to test logs
- Added locale English Malaysia
- Added locale English New Zealand.
- Added support for future remote application management.

Codependency with Other Products and Software:

| Product Name | Comments |
|----------------------|----------------------------|
| Kramer Control Brain | Recommended version 2.10.9 |



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes History

Product Name: KT-20x Touch Panels

Current Version:

| Type | Number | Date |
|----------|---------|--------------|
| Firmware | 1.11.38 | January 2023 |
| Hardware | - | — |

RN Date: January 2023

Reference: 019423

Bugs Fixed:

| QC ID | Deferred Bug Description |
|-------|--------------------------|
| N/A | |

Preceding Version: 1.11.22



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com