



Release Notes

Product Name: PA-120Z, PA-240Z

Current Version: Type

Туре	Number	Date
Firmware	R1.15.54548	November 2019
Software	1	_
Web	_	_
Hardware	_	_

RN Date: November 4, 2019

Reference: 15811

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
PA-120Z	Any	Yes	Yes
PA-240Z	Any	Yes	Yes

Technical Notes:

- Added one and improved one Protocol 3000 command.
- New features are described in the updated User Manual.

Codependency with Other Products and Software:

There is no codependency with other products or software.





Release Notes

Product Name: PA-120Z, PA-240Z

Current Version: Type

Туре	Number	Date
Firmware	R1.15.54548	November 2019
Software	_	_
Web	_	_
Hardware	_	_

RN Date: November 4, 2019

Reference: 15811

The following changes were made in this version:

New Features:

New I	New Feature Description		
_	New AUD-MUTE Protocol 3000 command: In addition to the current MUTE command. See below.		
AUD-	MUTE		
Func	tions	Permission	Transparency
Set:	AUD-MUTE	End User	Public
Get:	AUD- MUTE?	End User	Public
Desc	ription	Syntax	
Set:	Set audio mute	#AUD-MUTE[SP]stage,	channel, mute_mode[CR]
Get:	Get audio mute	#AUD-MUTE?[SP]stage	,channel[CR]
Resp	onse		
~nn@	AUD-MUTE [SP]stage,channel,mut	e_mode[CR][LF]
Parameters			
stage - 0 (Input), 2 (Output) channel - For input: 1 (Input 1), 2 (Input 2), * (Both channels); For output: 1 (Speaker output), 2 (Line level output), * (Both channels) mute mode - 0 (Off), 1 (On)			
K-Config Example			
Mute input 1: "#AUD-MUTE 0,1,1",0x0D			



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>





Release Notes

Modifications:

QC ID	Modification Description
	AUD-MIX Protocol 3000 command: Added values changing the level incrementally by 1dB and by XdB.
	++ – (increase current value by 1dB); – (decrease current value by 1dB)
	++X – (increase current value by XdB);X – (decrease current value by XdB)

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
11079	In web pages: Q-Factor parameter validation issue
11099	Web pages: The application does not support Internet on Android mobile
11230	In web pages: The Firmware Upgrade and Security tabs do not display in Safari on MacBook

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed.

Preceding Version: 1.10.50707





Product Name: PA-120Z

Current Version: Type

Туре	Number	Date
Firmware	1.10.50707	December 2018
Software	_	_
Web	_	_
Hardware	_	_

RN Date: December 2018

Reference: 14793

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
PA-120Z	Any	Yes	Yes

Technical Notes:

Fixed a bug.

Codependency with Other Products and Software:

• There is no codependency with other products or software.





Product Name: PA-120Z

Current Version: Type

Туре	Number	Date
Firmware	1.10.50707	December 2018
Software	_	_
Web	_	_
Hardware	_	_

RN Date: December 2018

Reference: 14793

The following changes were made in this version:

Bugs Fixed:

QC ID	Fixed Bug Description
	Stereo down mix setting no longer resets after power off(recycling).

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
11079	In web pages: Q-Factor parameter validation issue
11099	Web pages: The application does not support Internet on Android mobile
11230	In web pages: The Firmware Upgrade and Security tabs do not display in Safari on MacBook

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed.

Preceding Version: 1.9.47150



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>





Product Name: PA-120Z

Current Version: Type Number Date

 Firmware
 1.9.47150
 April 2018

 Software

 Web

 Hardware

RN Date: April 2018 Reference: 13912

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
PA-120Z	Any	Yes	N/A

Technical Notes:

Added features and fixed bug.

Codependency with Other Products and Software:

There is no codependency with other products or software.





Product Name: PA-120Z

Current Version: Type Number Date

туре	Number	Date
Firmware	1.9.47150	April 2018
Software	_	_
Web	_	
Hardware	_	_

RN Date: April 2018 Reference: 13912

The following changes were made in this version:

New Features:

New Feature Description
Protocol 3000 command AUD-LVL now enables changing volume by one dB with ++/ parameter.
Protocol 3000 command AUD-LVL now enables changing volume by X dB with ++X/X parameter.

Bugs Fixed:

QC ID	Fixed Bug Description
	Volume command no longer allows alphabetic parameter.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
11079	In web pages: Q-Factor parameter validation issue
11099	Web pages: The application does not support Internet on Android mobile
11230	In web pages: The Firmware Upgrade and Security tabs do not display in Safari on MacBook

Known Limitations (including compatibility limitations):

QC ID	Limitation Description	
	None listed.	

Preceding Version: F - 1.8



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com





Product Name: PA-120Z

Current Version: Type Number Date

Type	Number	Date
Firmware	1.8	April 2018
Software	_	-
Web	_	
Hardware	_	_

RN Date: April 2018 Reference: 11005

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
PA-120Z	N/A	N/A	N/A

Technical Notes:

• This is a release note for a new product.

Codependency with Other Products and Software:

There is no codependency with other products or software.





Product Name: PA-120Z

Current Version: Type Number Date

туре	Number	Date
Firmware	1.8	April 2018
Software	_	-
Web	_	_
Hardware	_	_

RN Date: April 2018 Reference: 11005

This is a release note for a new product. For a list of new product features see: www.kramerav.com/manual/PA-120Z

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
11079	In web pages: Q-Factor parameter validation issue
11099	In web pages: The application does not support Internet on Android mobile
11230	In web pages: The Firmware Upgrade and Security tabs do not display in Safari on MacBook

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com