

## Release Notes

**Product Name:** TP-873xr, TP-874xr

**Current Version:**

Type	Number	Date
Firmware	190124	February 2019
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** February 2019

**Reference:** 13377

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
TP-873xr	N/A	N/A	N/A
TP-874xr	N/A	N/A	N/A

### Technical Notes:

- This is a release note for a new product.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** TP-873xr, TP-874xr

**Current Version:**

Type	Number	Date
Firmware	190124	February 2019
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** February 2019

**Reference:** 13377

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/TP-873xr>

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)